

Section 04. Capability List

Capability of PT.Bagas Nusantara Putra is Aircraft Interior that are :

- | | |
|-----------------------------------|--------------------------------------|
| 1.Refurbishing (BNPS-510) | 5.Relaminating (BNPS-501, 506 , 509) |
| 2.Repairing (BNPS-502 , 506, 508) | 6.Servising(BNPS-501, 503,510) |
| 3.Repainting (BNPS-507) | 7.Recondition(BNPS-501, 503,509,510) |
| 4.Remarking (BNPS-507) | 8.Recovering (BNPS-510) |

Scope of Aircraft Interior	Capability Process Number
Cockpit Area :	
Light & Marking Panel	2, 3 & 4
Lining	2 & 3 for hard lining,(2) for soft lining
Partition	2 and 3 or 5
Cockpit Furnishing	2&(3) for Ceiling, all Cover, glare shields, side panel and central panel.
Cockpit Door	2 & 3 or 5
Placard & Marking	4
Cabin Area :	
Sidewall	2 & 3 or 5
Stowage Bin	2 & 3 or(5) for panel,(6) and completed Locking System etc..
Passenger Service Unit	2 &(3) for panel,(6) and completed Locking System
Placard & Marking (Cabin Decal)	2, 3 and 4
Galley Assy	2, 6, 5 & 3
Lavatory Assy	2, 6, 5 & 3
Ceiling	2 ,3 or (5) of panel
Partition	2 , 3 or 5
Door Cover	2, 3 or 5
Carpet / Floor cover	8
Seats (Pilot & Co Pilot Seat, Attendant Seat & Passenger Seat)	
Reclining System	2
Frame	2 & 3
Locking System	6
Fairing	2 & 3
Arm Rest	2 & 7

Arm Cap	2 & 7
Tables & Locking	2 , 3 &6
Ashtray	2 & 7
Magazine Net	2
Seat Cover	1 , 8

PT. BANUP Approved



JOKO BUDI UTOMO
Date : 20TH Apr 2019